

Preliminary Schedule of IAPWS Meetings Dresden, Germany. 11th – 16th September 2016

(All technical meetings will be in the Steigenberger Hotel de Saxe, Dresden, Germany)

Sunday 11 Sept.	7:00 – 10:00 pm	Informal Get-together and Registration
Monday 12 Sept.	8:30am	Executive Committee - Opening Plenary Session
	10:00am	Coffee / Tea Break
	10:30am	TPWS/IRS/SCSW Joint Meeting
	(To set agendas for the week and to conduct IAPWS Business, thus allowing remainder of week for technical matters)	
	10:30am	PCAS and PCC Separate Meetings
	(To conduct IAPWS Business, thus allowing remainder of week for technical matters)	
	12:00pm	Lunch
	1:30pm.	TPWS/IRS/SCSW Joint Meeting
	1:30pm.	PCC and PCAS Separate WG Meetings
Tuesday 13 Sept.	8:30am	PCAS Workshop (other WG Members will be welcome)
	8:30am	PCC Workshop (other WG Members will be welcome)
	8:30am	TPWS/IRS/SCSW Joint Working Group Meeting
	10:30am	TPWS/IRS/SCSW Joint or Separate Meetings
	10:30am	PCC and PCAS Separate Meetings
	12:00pm	Lunch
	1:30pm	TPWS/IRS/SCSW Joint Meeting.
	1:30pm	PCC/PCAS Joint WG Meeting and Workshop
	3:30pm	PCC and PCAS Separate Meetings
Wednes. 14 Sept.	8:30 – 1:30	IAPWS Symposium
	(Steam, Water and Aqueous Mixtures in Energy and Process Engineering)	
	2:30 – 5:00	Technical Visit
	(DREWAG - Stadtwerke Dresden GmbH)	
Thursday 15 Sept	8:30am	IRS, SCSW and PCC Separate WG Meetings
	8:30am	TPWS/PCAS Joint WG Meeting
	12:00pm	Lunch
	1:30pm	Separate meetings of Working Groups
	(If needed to prepare for Executive meeting)	
	6:30pm.	IAPWS Dinner/Banquet.
	(Europa Ballroom of the Hilton Hotel Dresden)	
Friday 16 Sept.	9:00am	Executive Meeting (9:00am - 1: 00pm)
	(Will include at least one member from each National Delegation)	

TPWS - Thermophysical Properties of Water and Steam WG

SCSW - Subcommittee on Seawater

IRS - Industrial Requirements and Solutions WG

PCAS - Physical Chemistry of Aqueous Solutions WG

PCC - Power Cycle Chemistry WG

Barry Dooley
24th August 2016